

MAR 02 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office } ss.
Gogebic County }

For corners in

Gogebic
(County)

Located in:

Corner Code #

1. Public Land Survey

Section 11

T 44N R 41W K-3/4
T 019

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Received for record the
10th day of NOVEMBER

A. D. 1999 at 11:25 o'clock

11 m., and recorded in
Liber 7 of CORNERS

on page 262

Ramona Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Meander corner common to sections 11 & 12

I, John R. Garske in a field survey on Oct. 21, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by A. Merryweater, D.S., in June 1852

Original Corner: Wood Post

Original Bearing Trees:

18" hemlock S75°E 12 links

1973 - Survey by Robert Winat, RLS. CSM recorded, bearing trees:

6" maple N62°W 9.1 feet

30" hemlock N67°E 20.2 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 3/4" capped iron (WINAT) pipe at corner position. I accepted this as the meander corner on the south shore of Thousand Island Lake and set a monument with witnesses listed below.

Robert Winat RLS established this corner in a 1973 survey recorded at the Register of deeds. Winat measured 1989.26 south to the 1/4 corner section 11 & 12 which checks out with our measurements of 1989.27.

(Research on file)

DEED GROUP APPROVED

Richard P. Deahn 11/9/99
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the meander corner position I set a 2 1/2" x 30" aluminum pipe monument with a 3 1/4" dia. alum. cap over existing capped pipe, stamped to identify the corner from which I established:

Maple clump S89°E 18.89 feet
Dead 30" hemlock stump N69°E 21.0 feet ±
14" maple N60°W 9.32 feet
Steel sign post North 2.00 feet
5/8" x 30" capped iron rod - N50°-58'-16"W - 94.98 feet
5/8" x 30" capped iron rod - N72° - 32'-44"E - 52.58 feet

Signed by John R. Garske
Surveyor's Michigan License No. 28410

Date 11-9-99

