Register's Office LAND CORNER RECORDATION CERTIFICATE Gogebic County Filing Requirement of Act 74, Mich. P.A. 1970 Received for record the For corners in day of July Gogebic Corner Code ## Located In: A. D. 1995 at 1:35 0'clock m., and recorded in T 44N R 43W 1. Public Land Survey d CURNEN 601 . R Dage 263 R mora Cours, Sepatt R 2. Property Controlling T Register of Deed in Section S _ T _ ___R. _ R _ _ T .__ 3. Miscellaneous S Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _ 4. Lot No. 5. Private Claims ... C. C. 1 & 2 on Michigan Wisconsin State Line May 26, 1995 Richard L. Drahn a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: C.C. established 66 links SE from Mile #24 by A. Merryweather on Jaly 15, 1852. Original B.Ts -- Hemlock 18" N 55 E, 28 links, (18.48')--- Hemlock 14" n 20 W, 33 links, (21.78') Corner restored by Richard L. Drahn, R.L.S. 21564 on 6/9/75 from the remains of the two bearing trees and at record distance from Mile # 24. He set a 2" X

5' iron pipe with a 3" brass cap stamped to identify the corner. He blazed and scribed the following B.T.s -- 9" Sugar Maple N.75 E., 33.0 ft. --- 5" Yellow Birch N.11 E., 23.5 ft. --- 6" Yellow Birch N.26 W., 30.7 ft. --- 7' Steel

Rail North, 2.2 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner recorded in Liber 1, Page 127 of Corners on 1/27/76.

Corner monument and bearing trees recovered in good condition, as described below.

I & Dra

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described monument the 1975 B.T.s were recovered as:

THE OF MICH 32.96 feet N.73 E. 10" Sugar Maple N.14 E. 23.29 feet 8" Yellow Birch 9" N.24 W. 30.79 feet Yellow Birch N.02 E. 2.1 fee 71 Steel Rail

> Resource grade GPS Lat. 46-14.61 N Long. 89-38.17 W

June 2, 1995

___ Date _

Surveyor's Michigan License No. _

AD SUR! FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

RICHARD

L. DRAHN

SURVEYOR