

SURVEY & REMONUMENTATION

NOV 12 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic
(County)

Located In:

Corner Code ##

- | | | |
|------------------------------------|---------------------------|--------------|
| 1. Public Land Survey | T <u>45N</u> R <u>46W</u> | <u>E-1-2</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | <u>015</u> |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Closing Corner Sec's 4 & 5 on State Line; T.45 N., R.46W³

I, Richard L. Drahn in a field survey on September 25, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austen Burt on July 9, 1851. Original B.T.s --- 12" Sugar N.27 E. 13 Links (8.58') --- 14" Y. Birch N.09 W. 23 links (15.18') --- Corner position lays 11.21 chains (739.86') NW of Mile Corner No. 2½.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the two original B.T.s. The first is a large deep stump hole with pieces of decayed Sugar Maple wood; the second one is now a 24-30" decayed Yellow Birch stump. The 3.38 chains north to "Y. Birch 20") now a very large Yellow Birch stump decayed to well below ground line; the 11.95 chains north to "Y. Birch 8") now a decayed 18-24" Yellow Birch stump and the 11.21 chains SE to Mile Corner No. 2½ are all in accordance with the field notes of the original Government Survey.

Research form on file with Gogebic County Records.

PEER GROUP APPROVED

Richard L. Drahn 10/8/97
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a 3½" alum. cap stamped to indicate the corners position, and the following new B.T.s:

- | | | | |
|-----|-----------------|---------|--------|
| 5" | Sugar Maple | N.32 W. | 28.05' |
| 11" | Sugar Maple | N.08 E. | 27.08' |
| 7" | Sugar Maple | N.87 E. | 43.56' |
| 6' | Steel sign rail | N.01 E. | 1.59' |



Signed by Richard L. Drahn

Date September 29, 1997

Surveyor's Michigan License No. 21564

USFS BE-9

2.27

Register's Office } ss.
Gogebic County }

Received for record the
9th day of OCTOBER
A. D. 1997 at 10:50 o'clock
A m., and recorded in
Lib. 6 of CORNERS
on page 227
Ramon Collins Deputy
Register of Deeds

Register of Deeds Stamp & File Number

