MAR 02 2000

r corpore in	SECTION	+
corners in		ľ

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's iffice Cogebic County [Received for record the

Gogebic (County)	Located In:	Corner Code #
1. Public Land Survey	T_46N TR	843W M-7

12 day of MA 5 A. D. 1999 at 10:30 g'clock A m., and recorded in illes 7 of CORNERS

Register of Deads

2. Property Controlling in Section

og page 132 temora Collins Deput

3. Miscellaneous Property in Sec. T46NR42W


Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

Section Corner 13, 24, 18 & 19; T.46 N., R.42-43 W.

I, <u>Richard L. Drahn</u> in a field survey on <u>May 5, , 1999</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on 8/6/1847. Original B.T.s --- Sugar 16" S.71 E. 12 links (7.92') --- Spruce 24" N.45 W. 26 links (17.16') ---Sugar 18" N.60 E. 52 links (34.32') ---

Corner position restored by Richard L. Drahn, RLS 21564 on 8/1/85 by retracement measurement to recovered line trees north, south, east & west. Logging road construction has destroyed the original corner and B.T.s. He set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ " stamped aluminum cap and the following new B.T.s: --- 6" Sugar Maple N.24 W. 29.97' --- 6" Sugar Maple

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

S.62 W. 55.59' --- 8" Sugar Maple S.28 E. 31.75' --- 6' Metal sign post S.53 E. 2.26'

Corner recorded in Gogebic County Liber 2, Page 732 on 1/10/86.

Recovered the monument as described and the bearing trees as follows:

Sugar Maple N.22 W. 29.91 7 ¹¹

Sugar Maple Sugar Maple S.62 W. 55.621 (new nail) 10" S.29 E.

31.74' 61 Steel sign rail S.55 E. 2.26'

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing tree referenced:

8 11

Sugar Maple

N.83 E.

57.44'

Date May 6, 1999

OT MICH RICHARD L. DRAHN LAND SURVEYOR 21564 LAND

Surveyor's Michigan License No. 21564

USFS N-25