

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic Located In: Corner Code #
 (County)

1. Public Land Survey T 46N R 44W. B-9
 T R
 T R
 T R

2. Property Controlling S T R
 in Section S T R

3. Miscellaneous S T R
 Property in Sec. S T R

**SURVEY &
 MONUMENTATION**

JAN 05 2001

SECTION

Register's Office } ss.
 Gogebic County }

Received for record the
26th day of MAY
 A. D. 2000 at 10:35 o'clock
1 m., and recorded in
 Liber 7 of CORNERS
 on page 281
Casper P. Ruppel
 Dep. Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

1/4 Corner 19 & 30; T.46 N., R.44 W.

I, Richard L. Drahn, in a field survey on April 27, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 Original corner established by Austin Burt on 8/17/1851. Original bearing trees:

Hemlock	12"	S.13° E.	9 links	(5.94')
Yellow Birch	8"	N.33° W.	34 links	(22.44')

Corner position restored by Richard L. Drahn, RLS 21564 on 5/26/83 from the remains of the two original B.T.s and line trees and natural feature ties east and west. He set a 3/4" X 6" aluminum rod with a stamped 3 1/4" aluminum cap and the following new B.T.s:

Yellow Birch	13"	N.12° W.	35.38'
Black Ash	6"	S.02° W.	36.66'
Hemlock	12"	S.83° W.	34.84'
Steel sign rail	6'	N.08° E.	1.22'

Corner recorded in Gogebic County Liber 2, Page 541 on 1/26/84.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner research on file with Gogebic County records.

Recovered the monument as described and the bearing trees as follows:

Yellow Birch	15"	N.11° W.	35.37'
Black Ash	8"	S.04° W.	36.61'
Hemlock	15"	S.84° W.	34.99' (new nail)
Steel sign rail	6'	N.07° E.	1.22'

The original Hemlock B.T. is now only fragments of decayed Hemlock wood in root holes. A stump hole remains from the Y. Birch.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing tree referenced:

Black Ash	5"	S.68° E.	24.41'
-----------	----	----------	--------

PEER GROUP
Richard L. Drahn 05/24/00
 COUNTY REGISTER

Signed by Richard L. Drahn Date April 28, 2000

Surveyor's Michigan License No. 21564
 USFS R-3

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1976

REVISED JAN., 1983

