

MAR 02 2000

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic  
(County)

Located In:

Corner Code #

## 1. Public Land Survey

T 46N R 46W

C-7

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Section Corner 17, 18, 19 &amp; 20; T.46 N., R.46 W.

I, Richard L. Drahn, in a field survey on October 28, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt on 6/23/1851. Original bearing trees:

Cedar	12"	S.43° E.	18 links	(11.88')
Cedar	14"	N.47° W.	31 links	(20.46')

C.. Supercynski, on 5/28/35 recovered both B.T.s scribed. He set a location poster on the east side of a 6" Cedar, from which a stake lay N.70°W. 20 feet.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The corner position was found marked by the 18" long point of the original post. The S.43° E. Bearing tree is now a shallow windthrown stump hole. The N.47° W. B.T. is now a cut, decayed Cedar stump with the GLO blaze and the measuring notch still visible. The Cedars in this area have all been cut, no evidence remains of the 1935 location poster or tag tree.

The 1.22 chain distance east from corner to leave swamp, N-S is in accordance with the field notes of the original survey.

A 4" X 4' Cedar post bears N.69° W., 18.35' from the original corner position.

corner research on file with Gogebic County records.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4" x 4' aluminum rod monument with a 3 1/4" stamped aluminum cap and the

Following new B.T.s (all measurements taken to a nail in side of tree)

Cedar	9"	N.37° W.	20.62'
Cedar	5'	S.67° E.	12.82'
Cedar	8"	S.16° W.	3.70'
Steel sign rail	6'	North	2.28'

DEED GROUP APPROVED

Richard L. Drahn 11/9/99  
COUNTY REGISTERED 11/9/99

Signed by Richard L. DrahnDate November 7, 1999Surveyor's Michigan License No. 21564

28, 1971

14, 1976  
JAN., 1983

USFS N-5

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN.  
REVISED MAY  
REVISED

REVISED OCT., 1995