

SURVEY &
REMONUMENTATION

SEP 08 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic

(County)

Located in:

Corner Code #

1. Public Land Survey

T47N R44W

I-10

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter Corner, Sections 26 & 27, T47N, R44W

I, John P. Goss, in a field survey on June 16, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

PEER GROUP APPROVAL

Richard L. Deahn 6/17/98
COUNTY SURVEYOR

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt, U.S. Deputy Survey, in 1848.

Original bearing trees: Hemlock 10" S 80° E 05 links
Sugar Maple 20" N 45° W 15 links

On October 15, 1969, Donald D. Lappala, RLS, USFS, restored corner position at record bearing and distance from the remains of the two original bearing trees. The first was a live 28" hemlock with scribing visible in G.L.O. blaze. The other a stump hole. He set a 2½" iron pipe with a 3" circular bronze tablet which indicated corner position. He established the following reference objects:
6" Elm - N 30° W - 24.8' (now a stump); 5" Elm - N 77° E - 40.9' (now out);

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

10" Yellow Birch - S 10° W - 23.0'

He recorded said corner in Forest Service Record book in Register of Deeds Office for Gogebic County. T-17 under T.47 N., R.44 W.

Original bearing tree is now a live 31" Hemlock with scribing visible in G.L.O. blaze.

Found Donald D. Lappala, monument and two witnesses.

I updated the monument and accessories as noted below to state and county specification.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From found 2½" dia. iron pipe with 3" circular bronze tablet which reads: T.47 N R.44 W., 1/4; S-26, S-27; R.L.S. 12585; 1969, from which I established the following existing and new reference objects:

18" Yellow Birch S 10° W 22.78'

6" Maple N 78° E 50.44'

6" Maple N 69° W 10.18'

6' Rail & sign Due West 1.56' (to face)

(All measurement taken to nail in side of tree)

Register's Office
Gogebic County

Received for record the
10TH day of JUNE

A. D. 1998 at 1:20 o'clock
P. M. and recorded in

Lib. 7 of CORNERS

on page 1

Ramona L. Collins Dep.

Register of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by John P. Goss

Surveyor's Michigan License No. 23509

USFS, No. T-17

Date June 16, 1998

