STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

				Houghton	1	COUNTY
			Τ _	51N	_ R	
DESCRIPTION OF CORNER	1/4 corner between 8	Sections 13	and	14		
CORNER MONUMENT1"	I.D. x 36" iron pipe	with 4" alu	minu	и сар		
DATE MONUMENT PLACED AND	WITNESSED Novemb	oer 5, 1970				
WITNESSES TO CORNER	. Hemlock 11	s 9°w 20.1	ft.	"1/4S,	NBT"	
N	Sugar Maple 12	888°W 8.1	ft.	"1/4S,	NBT"	
	AND					
CIRCLE CORNER REGISTE	RED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established on line between section corners 39.708 ch. to N and to S. Found a 1" I.D. iron pipe possibly intended to be this corner, but established N10 W 1.19 ch. from it, with no evidence of any kind to support it as being at the site of the original corner. Also found a 2"x2" squared maple post 5-10 years old, bearing N33°E 26 links, for another approximate corner.

SURVEYOR'S SEAL

DISTRIBUTION: SIGN

SIGNED

REGISTERED LAND SUPPEYOR

DATE March 24, 197

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68