

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 51N N. R. 36W


Houghton COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 26-35

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 9-17-62

WITNESSES TO CORNER..... 6" Hard Maple (1/4 S NBT) North 32 1/2 links



5" Hard Maple (1/4 S NBT) S69°E, 15 1/2 links

5" Hard Maple (1/4 S NBT) S40°W, 17 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced at old wood post, down and badly rotted. Found sugar stump bearing N4°W, 08 links with 48" W. Pine stump for line tree 1.31 chs. to west of corner. Distance checks to stream 24.00 chs. west.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 26, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler