

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 25 T 52N R 35W	8
	S T R	(GCDB 620240)
	S 25 T 52N R 35W	13
3. Miscellaneous Property in Sec.	S T R	(GCDB 660220)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10/14/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 25) Center-West 1/16 corner, Section 25. Not previously monumented.

(13-Sec. 25) Southeast 1/16 corner, Section 25. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 25) Established the position for the corner midway and on a straight line between Center of  
Section 25 1335.24' east and Quarter corner K10 1335.24' west.

(13-Sec. 25) Established the position for the corner at the intersection of straight lines  
connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Sugar N33°E 7.75' mrkd "1/16S BT"  
6" Maple in clump S68°E 13.0' do  
7" Sugar S25°W 16.9' do  
5" Sugar S81°W 12.05' do  
Set sq'd cedar post adjacent.  
E= 7870799.255 N= 233683.297

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" twin Maples N06°E 20.3' mrkd "1/16S BT"  
18" Cedar N51°E 31.1' do  
3" W.Pine S68°W 10.4' do  
10" Maple N19°W 29.9' do  
Set sq'd cedar post adjacent.  
E= 7871601.864 N= 233272.451

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/11/2015

For the Michigan Department of Natural Resources, Forest Resources Division