

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 52N R 35W	1
	S 28 T 52N R 35W	2
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 03/28/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,
monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 28) West 1/16 corner between Sections 21 and 28. Not previously monumented.

(2-Sec. 28) East 1/16 corner between Section 21 and 28. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 28) Established the position for the corner midway and on the Section line between Section
corner 1345.05' west and Quarter corner 1345.05' east.

(2-Sec. 28) Established the position for the corner midway and on the Section line between Quarter
corner 1345.61' west and Section corner 1345.61' east. The position for the corner falls in a water-
filled pit and could not be monumented properly. Established a WITNESS CORNER to the 1/16 corner
15.00' west of the corner position and on the Section line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Sugar N22E 18.65' mrkd "1/16S BT"
12" Sugar S65E 9.25' do
12" Maple S13W 19.35' do
12" Sugar N55W 29.8' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
15.00' west of the corner position and on the
Section line, for a WITNESS CORNER.
Set measuring nail with MDNR tag in the side of:
6" Y.Birch N11W 2.4' mrkd "WC BT"
8" Maple N42E 19.95' do
4" Y.Birch South 7.25' do
5" Sugar N86W 18.4' do
Set sq'd cedar post adjacent. Bearings magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/05/2012

For the Michigan Department of Natural Resources, Forest Resources Division

