

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: Oct. 4, 2016

For corner(s) in: Houghton County

Original Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

Property Corner

1/16 Corner Code

a. S 30 T 52N R 36W
a. S T R
b. S 29 T 52N R 36W
b. S T R

8 (GCDB 120240)
5 (GCDB 240260)

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Center-West 1/16 corner, Section 30. Not previously monumented.

b.) Center-North 1/16 corner, Section 29. A 1-1/2" ID iron pipe was found by the undersigned in 1998. Found no other record.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Established the position for the corner on the E-W 1/4 line of Section 30 1335.35' west of the monumented Center of Section 30 and 1380.08' east of the Quarter corner, the position being proportionate to the dimensions derived from the GLO original plat of this township.

b.) Found a 1-1/2" ID iron pipe, projecting 1.7' above ground substantially midway and on a straight line between the Center of Section 29 and the North 1/4 corner of Section 29. Found 4 trees with overgrown blazes facing the pipe, in the sides of which were found nails with tags PS #32336. Accepted the pipe as a careful and faithful determination of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" W.Pine N58°E 7.1' mrkd "1/16S BT"
6" W.Pine S19°W 15.3' do
7" W.Pine S89°W 8.0' do
8" Maple N20°W 12.5' do
Set sq'd cedar post adjacent.
E= 7853116.478 N= 234062.566

(b.) Found 1-1/2" ID iron pipe.
Found measuring nails with tags #32336 in:
9" Sugar N26°W 16.6' overgrown blazes
12" Sugar N82°E 18.5' do
10" Sugar S06°E 14.6' do
9" Sugar S72°W 14.95' do
Set sq'd cedar post adjacent.
E= 7855141.150 N= 234398.854

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.
Coordinate Reference: NGS PID RL0502, E= 7857774.767 m. N= 234995.272 m.

Stephan J. Szyszkoski

11/03/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

