

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See Below

For corner(s) in: Houghton

County

Original Public Land Survey Corner

Corner Code

S _____
S _____
S _____
S _____

T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____

Property Corner

a. S 31
a. S 36
b. S 31
S _____

T 53N R 33W
T 53N R 34W
T 53N R 33W
T _____ R _____

1/16 Corner Code

3 (GCDB 100160)
7 (GCDB 700160)
B12 (GCDB 140140)

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) The North 1/16 corner between Section 31 T53N-R33W and Section 36 T53N-R34W. Not previously monumented.

b.) The Center of Section 31. Not previously monumented.



Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Nov. 13, 2017. Established the position for the corner midway and on the Range line between Section corner 1316.63' north and Quarter corner 1316.63' south. The position for the corner falls adjacent to a seemingly unstable rock ledge. The position being unsafe, a WITNESS CORNER was established 27.53' north of the corner position, on the Range Line.

b.) Nov. 8, 2017. Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. Quarter corner C12 is not monumented and access to it is very difficult. In 1980, K.L.Sackett RLS, for a subdivision of Section 32, calculated its position as being midway and on line between Section corners C11 and C13. I have done the same here: The position of C12 is calculated as being midway and on the Section line between Section corners C11 and C13 2616.60' north and south.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap at the WITNESS CORNER.

Set measuring nail with MDNR tag in the side of:

7" Sugar N48°E 10.95' mrkd "WC BT"
11" Maple S37°E 8.45' do
7" Y.Birch S08°E 5.9' do
13" Maple N40°W 13.25' do

Set sq'd cedar post adjacent.

E= 7881852.54 N= 241925.86 (The W.C.)

b.) Set 1"IDx28" I.pipe with plastic MDNR cap.

Set measuring nail with MDNR tag in the side of:

7" Y.Birch S63°E 34.95' mrkd "C1/4 BT"
9" Y.Birch S23°E 30.6' do
4" Hemlock S12°W 21.2' do
8" Y.Birch N06°W 24.7' do

Set sq'd cedar post adjacent.

E= 7882653.06 N= 241501.38

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Stephan J. Szyszkoski

01/11/2018

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908