

Nov. 6, 1998  
Robert W. Crampton

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
HOUGHTON  
(County)

Located in:

Corner Code #

SURVEY &  
RECORDATION

DEC 14 1998

1. Public Land Survey

T 53W R 33W

T 53W R 33W

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

MEANDER-7  
MEANDER-6

Seg. 1

ROBERT F. MIKESCH 11/16/98  
HOUGHTON COUNTY, REGISTER 14:45  
LC 3/ 543 PAU Fee: 9.00  
Page 1 of 1

4. Lot No. , Recorded Plat

5. Private Claims

I, R. W. CRAMPTON, in a field survey on OCTOBER 30, 19 98  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

MEANDER-7, SET MEANDER POST ON LEFT BANK (NO WITNESSES)  
MEANDER-6, SET MEANDER POST ON RIGHT BANK, NO TREES FOR BEARING

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MEANDER-7, SET 1 1/4" IRON PIPE WITH 2 1/4" BRASS CAP ON LINE BETWEEN SE CORNER AND SW CORNER  
OF SECTION 2, 50' FROM THE WATER'S EDGE OF PORTAGE CANAL ON THE WEST BANK.  
S89°53'44"E 1600.60' FROM SAID SW CORNER.

MEANDER-6, SET 1 1/4" IRON PIPE WITH 2 1/4" BRASS CAP ON LINE BETWEEN NW MEANDER CORNER ON  
WEST SECTION LINE OF SECTION 2 AND THE SW CORNER OF SECTION 2, 100' FROM WATER'S  
EDGE OF PORTAGE CANAL ON SOUTH BANK N00°47'36"N 1666.01' FROM SAID SW CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MEANDER-7, THE 1 1/4" IRON PIPE WITH BRASS CAP WAS WITNESSED WITH SURVEY TAG NAILED TO:  
10" SPRUCE TREE N81°W 133.16', 14" SPRUCE TREE S16°E 193.79',  
14" W. BIRCH TREE S28°W 164.82', 14" W. BIRCH TREE S59°W 187.59'.

MEANDER-6, THE 1 1/4" IRON PIPE WITH BRASS CAP WAS WITNESSED WITH SURVEY TAG NAILED TO:  
12" W. BIRCH TREE N61°W 19.72', 8" W. BIRCH TREE N02°W 31.46',  
12" W. BIRCH TREE S28°W 20.10', 14" W. BIRCH TREE S62°W 22.58'.

Signed by Robert W. Crampton

Date Nov. 4, 1998

Surveyor's Michigan License No. 24591

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971  
REVISED MAY 24, 1975  
REVISED JAN., 1983

