

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Houghton Co.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>53N</u> N. S., R. <u>33W</u> E. W.	D11
2. PROPERTY CONTROLLING IN SECTION	T. <u>53N</u> N. S., R. <u>33W</u> E. W.	9, 16
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 6, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner D11: Original monument and accessories not found. Found old axe marks in area.
 - Corner 9: Not set on original survey nor subsequently apparently.
 - Corner 16: Not set on original survey nor subsequently apparently.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- Corner D11: Restored during section subdivision. Found this location best fits with other corners in area.
 - Corner 9: Established during section subdivision.
 - Corner 16: Established on line and midway between corners east and west.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D11: Set 4" squared cedar post in swamp.
 5" Tamarack S22°W 27.8 Ft. 1/4 S, NBT
 9" Tamarack S81°E 12.5 Ft. 1/4 S, NBT
 4" Maple N55°W 8.2 Ft. 1/4 S, NBT

Corner 9: Set 1" O.D. by 4-1/2 ft. fluted iron pipe in swamp.
 6" Tamarack S42°W 37.9 Ft. 1/16 S, BT
 5" Tamarack N67°W 29.7 Ft. 1/16 S, BT
 7" Maple N28°E 20.8 Ft. 1/16 S, BT

Corner 16: Set 4" squared cedar post in tamarack swamp.
 4" Tamarack N72°W 6.7 Ft. 1/16 S, BT
 6" Tamarack N75°E 10.5 Ft. 1/16 S, BT
 6" Tamarack S26°W 8.8 Ft. 1/16 S, BT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett DATE 2/6/80

CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR
 Keith L. Sackett
 Dept. of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

