

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: May 4, 2016

For corner(s) in: Houghton County

Original Public Land Survey Corner

Corner Code

a. S T 53N R 34W B11 (GCDB 140200)
S T R
S T R
S T R

Property Corner

1/16 Corner Code

b. S 30 T 53N R 34W 5 (GCDB 140260)
S T R
S T R
S T R

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Quarter corner common to Sections 30 and 31. 1846 - Deputy S.W.Higgins established the corner on the Section line between Section corners 40.00 chains east and 40.02 chains west. Set post. Spruce 12" S15°E 25 links, Spruce 10" N10°W 30 links. Circa 1920 - Engineers Gibbs and/or Fesing ran a line between A11 and E11 and reestablished a position for C11 but make no mention of this corner. 1922 - P.A.Larsen forester and surveyor reestablished the position for the corner on line between Section corners 2638.82' east (also reestablished by him, same date) and 2640.25' west (original corner), being proportionate to the original record. Set cedar post. No witnesses noted.

b.) Center-North 1/16 corner, Section 30. Not previously monumented.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) The original post and accessories were not recovered. Found no evidence of the 1922 survey nor of any subsequent perpetuation. Reestablished the position for the corner on the Section line between Section corners 2643.45' east and 2644.75' west, being proportionate to the original record.

b.) Established the position for the corner midway and on a straight line between Quarter corner 1372.86' north and the unmonumented intersection of 1/4 lines of Section 30, 1372.86' south.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
14" Spruce N16°E 12.6' mrkd "1/4S NBT"
4" Spruce S13°E 6.65' do
4" Cedar S23°W 22.95' do
12" Balsam N40°W 7.1' do
Set sq'd cedar post adjacent.
E= 7873013.403 N= 242486.710

(b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Cedar N56°E 15.6' mrkd "1/16S BT"
6" Y.Birch S47°E 13.0' do
4" Cedar S88°W 38.55' do
7" Sugar N16°W 19.4' do
Set sq'd cedar post adjacent.
E= 7873031.790 N= 243696.123

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.
Coordinate Reference: NGS PID DL5986, E= 7882233.252 m. N= 259878.551 m.

Stephan J. Szyszkoski

06/29/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

