

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County) Located In: Corner Code #
1. Public Land Survey T R
2. Property Controlling in Section S 36 T 53N R 35W 9 (GCDB 660140)
3. Miscellaneous Property in Sec. S 36 T 53N R 35W 12 (GCDB 640120)
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 10/06/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 36) Center-East 1/16 corner, Section 36. Not previously monumented.

(12-Sec. 36) Center-South 1/16 corner, Section 36. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 36) Established the position for the corner midway and on a straight line between Quarter corner 1313.70' east and Center of Section 36 1313.70' west. From the position thus established, I found a loosely-set 1-1/4" ID I.pipe N51°E 6.4' distant, which I removed and drove adjacent to the post at the established position.

(12-Sec. 36) Established the position for the corner midway and on a straight line between Quarter corner 1312.69' south and Center of Section 36 1312.69' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" Sugar N81°E 14.4' mrkd "1/16S BT" 12" Maple S43°E 26.65' do 9" Sugar S66°W 19.3' do 15" Y.Birch N21°W 34.1' do Set sq'd cedar post and 1-1/4" pipe adjacent. E= 7871792.460 N= 241729.490

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Y.Birch N65°E 2.0' mrkd "1/16S BT" 10" W'ly of twin Heml. S60°E 28.15' do 4" Cedar West 21.55' do 14" Hemlock N42°W 6.05' do Set sq'd cedar post adjacent. E= 7871379.853 N= 241333.463

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by [Signature] Date 11/04/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division