

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 36 T 53N R 35W	6
	S T R	(GCDB 660160)
	S 36 T 53N R 35W	2
	S T R	(GCDB 660200)
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10/12/15 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 36) Northeast 1/16 corner, Section 36.  
Found no record of prior monumentation.

(2-Sec. 36) East 1/16 corner between Sections 25 and 36.  
Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 36) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners, those to the north, east, and south being monumented. From the position thus  
established, found a squared post in a mound of rock N72°W 19 ft. distant. Removed the post and  
laid it on the ground adjacent to the established position.

(2-Sec. 36) Established the position for the corner midway and on the section line between Section  
corner 1299.59' east and Quarter corner 1299.59' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap in a  
mound of rock 1 ft. high and 18" in dia. Set  
measuring nail with MDNR tag in the side of:  
11" Sugar S66°E 1.9' mrkd "1/16S BT"  
4" Sugar S23°W 24.0' do  
10" Sugar S83°W 11.6' do  
12" Sugar N28°W 18.8' do  
Set sq'd cedar post adjacent.  
E= 7871802.554 N= 242131.410

(2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" Sugar N88°E 10.3' mrkd "1/16S BT"  
4" Sugar S02°E 10.05' do  
4" Sugar N82°W 9.95' do  
7" Sugar N03°W 14.7' do  
Set sq'd cedar post adjacent.  
E= 7871812.649 N= 242533.317

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by Stephan J. Szyszkoski Date 11/04/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division