| AF | PROVED LAND CORNE | R |
|----|-------------------------------------|---|
| \ | P.A. 345 OF 1990 Houghton County | _ |

| P.A. 345 OF 1990 |
|-------------------|
| A Houghton County |
| (X) I in A A |
| Dout W. Clay |
| 9/24/99 |
| |

JAN 2 5 2000

RE

LAND CORNER RECORDATION CERTIFICATE

| Fo | or corners | : in | Filing Requi | rement of Act 74, Mic | h. P.A. 1970 | ; | SECTION | | |
|-----------------------------|--|--|--|---|---|--------------------------------------|---|----------|--|
| | HÖ | UGHTON | Located In: | Corner Code # | | | | | |
| 1. | Public l | (County) _and Survey | T <u>55N</u> R <u>33W</u> T <u>7 R R</u> | 7)[JM-5) V | | N COUN | Ø9/27/9 FTY, REGI PAU Fee Page | STER 1 | 9. 1210 |
| | in Secti Miscella | | T R S T R S T R S T R | | Reg | ister of D | eeds Stamp & | File Num | ber |
| 4. | Lot No. | | Recorded Plat | | | | | | |
| | | | | | | - <u>A B</u> | CDEFG | <u> </u> | KLM |
| | hereby ce | ertify that under re | _ , in a field survey onequirements of P.A. 74, Michigan P conformance with regulations and | '.A. of 1970, the corner point | ts mentioned | 2 — 6 — 3 — 7 — 5 — 18 — 6 — 18 — | 8 9 | 101 | 1 12 |
| ma Ma 5 a De as | anual of s anagement above wer cree of a (expressed | survey instruction t or by a decree of e in conformance Court of Law; est I below: | ns of the United State's Depart of a Court of Law and/or that the o e with the rules of the Michigan E ablished, re-established, monume | ment of the Interior, Bure corner points mentioned in li Board of Professional Surve nted, re-monumented, reco | eau of Land nes 3, 4 and yors or by a vered, found | 7 8 — 19 — 9 — 10 — 30 — 11 | 29 - 28 | | 324 |
| ΝŲ | | t more than 4 co | orners, all in the same town an | d range, may be recorde | d | 12 31 - | 32 33 | 34 39 | 5——36— |
| A. | Descrip | otion of origina | I monument and accessories | and/or subsequent resto | oration: | | TOTALITA | TITA | |
| | I-9, | SET POST CO | DR OF SEC, SUGAR 10 N87E | 26, MAPLE 9 S21W 20. | · | Ē | TATE OF MI | CHICAN | λ |
| | 7, | LAKE, SET MI | EANDER COR. POST, FIR 14 | S67W 28. | | The The Transport | ROBERT CRAMPTO LAND SURVEYO NO. 24591 | R R | The second secon |
| В. | Descrip | otion of corner | evidence found and/or metho | d applied in restoring or | reestablishing | corner: | dillion | | |
| | I-9, | 1" IP (FND) F 2 ¼" BRASS (| ROM DIMENSION SHOWN (CAP. | ON THE PORPOSED ASS | SESSOR'S PLAT | OF MAS | ON. SET | | |
| | | | PIPE WITH BRASS CAP, ON FOLIO 27), ON THE EASTERL | | | | CITY, (PLAT | | |
| | | | | | • | | | | |

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 1-9, THE 1" IRON PIPE WITH BRASS CAP WAS WITNESSED WITH SURVEY TAG NAILED TO: 9" MAPLE TREE N20°W 110.39', UTILITY POLE N33°E 77.15'. 8" MAPLE TREE S61°W 71.25', 5" OAK TREE S73°W 30.43'.
 - THE 1" IRON PIPE WITH BRASS CAP WAS WITNESSED WITH SURVEY TAG NAILED TO: TWIN 10" W. BIRCH TREE N30°E 7.40', 6" BOX ELDER TREE S65°E 27.79', N86°W 100.70' TO 1/2" ROD W/CAP (S. HEIN), N65°W 11.55' TO 1/2" ROD W/CAP (R. HAATAJA).

| Signed by_ | Ralet | Wi | Ciain | Des . |
|------------|---------------|---------|-------|-------|
| Surveyor's | Michigan Lice | nse No. | 24591 | , V |