

APPROVED LAND CORNER
P.A. 74, Mich. P.A. 1970
Houghton County

Ronald W. Camp
Oct 28, 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

JAN 25 2000

For corners in
Houghton
(County)

Located In:

Corner Code #

SECTION

1. Public Land Survey T 55N R 34W
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

I-7

Mary Schoos

1P

Register of Deeds

Houghton County, Register

Page 1 of 1

LC 4/65

PAU Date 12/30/1999

Time 10:52:54

FFF

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Ronald S. Haataja, in a field survey on September 15, 1998,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I-7) NW corner Section 23, T55N-R34W
80.00 Set post corner of Sections 14, 15, 22, 23
References: Sugar 8" S09°E 26 lks.
Do 10" N52°W 25 lks.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4			3		2		
3												
4	7		8		9			10		11		12
5												
6	13		17		16			15		14		13
7												
8	19		20		21			22		23		24
9												
10	30		29		28			27		26		25
11												
12	31		32		33			34		35		36
13												



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I-7) NW corner Section 23, T55N-R34W
No evidence of original corner or accessories found.
Set 1" Hex Drill rod with bit at top from double proportioning
between the W 1/4 of Section 14 and the W 1/4 of Section 23, and
between the NW corner of Section 22 and the NE corner of Section 23.
Set during a field Survey on September 15, 1998.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-7) NW corner Section 23, T55N-R34W
1" Hex drill rod w/ bit at top. Drove 2" Aluminum pipe over
the drill rod and cemented on a brass Houghton County Remonumentation
cap.
Witnesses: Brass Tags PS#39478 nailed into side of trees.
3" Jack Pine S41°W 23.51'
3" White Birch N35°W 34.07'
7" White Birch N44°E 30.72'
4" Ash S16°E 62.71'

Signed by Ronald S. Haataja

Date October 20, 1999

Surveyor's Michigan License No. 39478