

JAN 19 2001

2000 REMONUMENTATION

Re-Monumented, Page 65

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron

(County)

Located in:

Corner Code #

STATE OF MICHIGAN
HURON COUNTY
RECORDED

20 SEP 2000 2:03 PM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey Sand Beach T16N R15E A-11
T R
T R
T R
T R
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Charles S. Getz, in a field survey on May 17, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L
1	6	5	4	3	2	1					
2											
3											
4	7	6	5	4	3	2	1				
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											


- A. Description of original monument and accessories and/or subsequent restoration:
A-11 1834 G.L.O., H. Parke D.S. County Road Commission Records - NONE
Set Post Recorded Surveys - NONE
Fir 10", S50 $\frac{1}{2}$ °W, 14 Links
Cedar 6", N29°W, 14 $\frac{1}{2}$ Links Unrecorded Surveys - Case, 10-21-99, 3/4" pin
L.C.R.C. - NONE

County Surveyor Records -
NONE

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
A-11
SW Cor, Section 30, T16N-R15E
Found 3/4" Iron Bar
Accepted as the best available evidence
of the original corner position
(Intersection of Puwalowski Road & Finkel Road)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11
SW Cor, Section 30, T16N-R15E
Found 3/4" Iron Bar
East 52.20' to Nail in Power Pole
East 30.55' to the South Leg of a Road Sign
N60°E 35.00' to a Cable Warning Post
S45°W 37.32' to a Stop Sign
North 2622.88' to W 1/4 Cor, Sec 30, T16N-R15E
South 2616.14' to W 1/4 Cor, Sec 31, T16N-R15E



Signed by Charles S. Getz
Surveyor's Michigan License No. 25843

Date June 10, 2000

PEER GROUP APPROVED AT MEETING
HELD September 18, 2000. PLB

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995