## SUMBER OF REMONUMENTATIO

Signed by

Surveyor's Michigan License No.

DEC 1 2 1997 LAND CORNER RECORDATION CERTIFICATE 9 Page Filing Requirement of Act 74, Mich. P.A. 1970 Liber 270 COMMISSION FILED INGHAM COUNTY Located In: Corner Code # (County) 970044062 WHITE OAK TOWNSHIP 11/05/1997 12:39:59 REGISTER OF DEEDS 1. Public Land Survey R 2E M-13 Paula Johnson INGHAM COUNTY, MI <u> MR2E</u> 2. Property Controlling in Section Т 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. \_ , Recorded Plat . 5. Private Claims 2 3 4 , in a field survey on OCTOBER 2 I. DAVID L. CLIFFORD Do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as 6 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points 7 mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1. JOSEPH WAMPLER D.S. SET POST IN ORIGINAL GOVERNMENT SURVEY IN NOVEMBER 1825: W.O. 14" \$19E 107LKS; W.O. 8" \$57W 97LKS 2. T.J. BROWN, COUNTY SURVEYOR, CALLED CORNER A POST IN A SURVEY RECORDED IN VOLUME 2 PAGE 329 IN JANUARY 1858 3. R. LESTER, RLS #18998, RECORDED CORNER IN LIBER 5 PAGE 237 IN APRIL 1979 AS A SET 4" X 36' CONCRETE MONUMENT WITH 1/2" X 38" REROD WITH CAP #18998. PART B OF THIS CERTIFICATE READS: EXCAVATED A HOLE 8' X 9' TO AN AVERAGE DEPTH OF 4', EAST OF THE CENTERLINE OF KANE ROAD AND ON A FENCE LINE TO THE WEST. FOUND A POINTED ROCK (4" X 20") WITH SLEIGH SHOE ALONG ITS NORTHWEST SIDE, + OR - 5.0' EAST OF THE CENTERLINE OF KANE ROAD AND ON A FENCE LINE TO THE WEST AND 4.5' NORTH OF THE FENCE LINE TO THE EAST. MEASURED NORTH + OR - 5335' TO M-11 IN CLOSE ACCORD WITH T.J. BROWN SURVEY NOTED ABOVE. ACCEPTED SLEIGH SHOE FOR CORNER, HE THEN LISTED 4 WITNESSES: NAIL & TAG #18998, NORTH SIDE 18" OAK, EAST, 212.32'; NAIL & TAG # 18998, EAST SIDE 5" RED CEDAR, SE, 28.71'; NAIL & TAG #18998, NE SIDE 6" CORNER POST, ESE, 20.95'; NAIL & TAG #18998, SW SIDE 6" WOOD GATE POST, WNW, 28.97' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND A 4" CONCRETE MONUMENT WITH 1/2" BAR & ILLEGIBLE CAP 3" EAST OF CENTERLINE KANE ROAD ON FENCE LINE TO WEST & 4.5' NORTH OF FENCE LINE TO EAST. ACCEPTED MONUMENT AS PERPETUATION OF CORNER BASED ON R. LESTER'S LCRC INFORMATION & CAPPED IT WITH PA 345 CAP. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner M-13 T2N, R2E

4" CONCRETE MONUMENT & YELLOW PLASTIC CAP IMPRINTED PA 345 PS 25837

FOUND NAIL & TAG #18998 NORTH SIDE 19" HICKORY, 95° NAZ, 212.29'

SET NAIL & TAG #25837WEST SIDE 5" HICKORY, 150° NAZ, 33.18'

FOUND NAIL & TAG #18998 NE SIDE GATE POST, 297° NAZ, 29.13'

FOUND NAIL & TAG #28414 (M. MAHIEU) WEST SIDE 10" CEDAR, 140° NAZ, 28.35'

FOUND NAIL & TAG #28414 SOUTH SIDE ANCHOR POST, 275° NAZ, 26.76'

FOUND LARGE SPIKE NE SIDE GATE POST, 320°, NAZ, 39.21'

NO. 25837 16, 1997 FOUND NAIL & TAG # 28414 NORTH SIDE RAILROAD TIE ANCHOR POST, 110° NAZ, 20.85°

> FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983

Date OCTOBER 16.