## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY T. 6, R. 7 W.	3-E	7
2. PROPERTY CONTROLL- 4, T. 6, R. 2 W.	3-E	Ionia
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.		
4. LOT NO, RECORDED PLAT		
5, PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1971, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:		
A. Description of original monument and accessories and/	or subsequent restoration:	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  FROM INFORMATION FURNISHED BY COUNTY ROAD COMM,  FOUND NAIL FTAG IN INTERSECTION OF DAVID HAY, FHARTWELL RA  SET RAIL ROAD SPIKE.		
C. Description of monument for corner and accessories e  N60°W 50.3' SIGN FO	ファイ	١
556°W 51.15' FOWER F. 572E 117.30' 30" MA N 70°E 64.15' TELEPHO	NE POLE PKINAL	BRASS WASHER  FISHASS WASHER
SIGNED BY	DATE	June 7/
SURVEYOR'S MICHIGAN REGISTRATION NO.		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:		
SIGNED BY CHIEF OF SURVEY PARTY	DATE	<u> </u>
APPROVED AND SIGNED BYMICHIGAN REGISTERED LA	DATE	(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.