durated a REMONUMENTATIO:

DEC 0 2 1997

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

			Filing Ret	quirement of Ac	Ct /4, Milcii. F./	1. 1370							
CC	MMISSIO		_			1 17	TER	003	r B PAG	E 32.	Ĵ		
For corners in IONIA		Located In:	Corne	er Code #		h-1	<u> 35-11</u>	2 -	,				
(County) 1. Public Land Survey			<u>W_</u>	K-9					TOP RECEIV		HIBAN NTY RECOR		
Property Controllin in Section Miscellaneous Property in Sec.	s s s s	T R R T R R R R R R R R R R R R R R R R				Regi	istei		eds:S	amp 8		umber	·
	Decerted Plat						, A	. в С	; D	F G	, н і	J K	L M
4. Lot No 5. Private Claims	, neconied ; id:						2	6	5	4	3	2	1
prpx 24 40 0 7						3 4	7	8	9	10	۱۱	12	
I. MARINUS MULDER , in a field survey on SEPT. 24, 19.9.7, the corner points mentioned in do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in the lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Current manual of survey instructions of the United States Department of the Interior, Bureau of Land Surveyors or by a decree of a Court of Law and/or that the corner points mentioned in tines 3, 4 and 5 management or by a decree of a Court of Law and/or that the corner points mentioned in the lines of the Michigan Board of Land Surveyors or by a Decree of a above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a							5 6	18	17	16	15	14	13
							7 8	19	20	21	22	23	24
Court of Law; established, re-established, expressed below:						au, Iouna as	9 10	30	29	28	27	26	25
NOTE: Not mor	e than 4 corners, a certificate.	all in the same tow	n and range	e, may be records	ed		11 12	31	32	33	34	35	36
		nd accessories and/o ISHED BY U.S. DEP 10" BEECH N22°E			OOKFIELD IN 18 CH S85°W 20 LII	37. A WOOD NKS.	13		<u></u>		<u> </u>		
THERE IS NO REC	ORDED INFORMA	TION IN THE COU	NTY SURV	EYOR RECORDS	FOR K-9.								
					O THE COMME	Y ROAD COMMIS	SION	WITNE	SSES F	OR K-9 I	DUND (IN THE	SECTIO

THE IONIA COUNTY ROAD COMMISSION IMPROVED HAWLEY HIGHWAY IN 1959. THE COUNTY ROAD COMMISSION WITNESSES FOR K-9 FOUND ON THE SECTION CORNER INDEX MAP IS: 10" ELM N.E. 43.53 FEET; 30" ELM W.N.W. 38.25 FEET; 24" MAPLE N.E. 57.35 FEET; 30" MAPLE N.W. 44.82 FEET

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: AT THE INTERSECTION OF HAWLEY HIGHWAY AND A FENCE LINE EAST AND WEST FOUND A RAILROAD SPIKE ON THE PAVEMENT SURFACE. ONE OF THE COUNTY WITNESS TREES REMAIN BEING THE 30" MAPLE N.W. MEASURED 43 FEET TO THE MAPLE. EXCAVATED BENEATH THE SPIKE AND AT A DEPTH OF 6" FOUND A 3/4" x 6" BOAT SPIKE. BELOW THE BOAT SPIKE FOUND A 5/8" SQUARE STEEL ROD 20" LONG, WITH BROKEN PIECES OF BRICK AT ITS BASE. NO OTHER EVIDENCE WAS FOUND.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET A 24" MONUMENT WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY-25863" IN PLACE OF THE EXISTING MONUMENTATION WITNESSED BY:

NAIL & TAG

EAST SIDE 42" MAPLE N30°W 43.07 FEET

NAIL & TAG

SOUTH SIDE POWER POLE \$88°W 60.38 FEET

NAIL & TAG

WEST SIDE 24" MAPLE N18°E 68.48 FEET

CENTERLINE 3" HICKORY S42°E 70.00 FEET

ROAD CENTERLINE ± 1 FOOT WEST

Signed by Merris a. mulder	Date 11-12-97
	FORM APPROVED BY MICHIGAN 51 ATE BOARG OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
Surveyor's Michigan License No. 25863	ADAPTED FOR WORD PROCESSING MARCH, 1913



Ridfield by Long Coup P.A. 395 Mine C. may

Date 10 - 29 - 97 Marinus A. Mulder, Chairman