

1993

REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ionia (County) Located In: Corner Code ##

1. Public Land Survey T 8N R 6W B-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Marinus Mulder, in a field survey on July 7, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner first set by Orange Risdon U. S. Deputy Surveyor between November 30, 1830 to July 23, 1831. Set wood post witnessed by (1) 14" White Oak N 30° E 18 links
(2) 12" White Oak S 37° W 1.42 chains

No history of perpetuation

The plat of Woodard Park surveyed by Lawrence Hale in 1922 shows a tie to this corner, but does not state what it is.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On the bituminous road surface found standard Ionia County Road Commission nail & tag. Excavated road bed and at a depth of 15" found boat spike and at a depth of 30" below road surface found large pile of stones. More than likely the County Road Commission set the boat spike while improving Woods Road. The position fits occupation very good. This is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 30" long fiberglass monument with a 4" brass cap stating "Ionia County Survey Monument" over the stone pile.

Witnesses:

Nail and tag West side 28" Maple N 8° E 51.65'
Nail and tag Northwest side 28" twin Maple S 55° W 53.03'
Nail and tag Northeast side 34" Oak S 40° E 42.25'
Nail and tag Southwest side 30" Maple N 55° W 42.61'

LIBER 003 PAGE 22

Signed by Marinus Mulder Date August 30, 1993

Surveyor's Michigan License No. 25863