

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

IOSCO

(County)

Located In

Corner Code #

1. Public Land Survey T 24N R 8E L-5  
T R
2. Property Controlling in Section S T R  
S T R
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on April 13, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-5 Quarter corner common to Secs. 12 & 13, T24N,R8E

1843 – GLO – Mullett & Burt – Set quarter section post.  
Wit: Alder 6 N82°E 10 links  
Tamarack 6 S62°W 20 links

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-5 Quarter corner common to Secs. 12 & 13, T24N,R8E

Searched area well, but found no evidence of any corner. Searched for possible square cedar stake or State of Michigan monument from 1926 Dept. of Transportation survey. Set 4" stamped aluminum DNR cap on 1"x6' galvanized pipe by single proportionate measurement. Accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-5 Quarter corner common to Secs. 12 & 13, T24N,R8E

Set 4" stamped alum. DNR cap on 1"x6' galvanized pipe.  
Wit: N63°E 10.95' to set N&T on NW side 10" Cedar  
S19°E 10.98' to set N&T on SW side 6" Cedar  
S45°W 12.77' to set N&T on W side 6" B. Spruce  
N43°W 28.81' to set N&T on NE side 8" Cedar  
Set Blue Carsonite Post 1' North



Signed by:

Carl T Kiiskila

Date:

8-10-09

Surveyor's Michigan License No.:

33981