FEB 1 6 1998

8" JACK PINE \$ 15° W 22.43

Surveyor's Michigan License No. 25882

WILLIAM E. WOODS P.S.

Signed by .

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

	Filin	ig Requirement of Act 74, when a	
SECTION		REMONUMENTATION CORNER Corner Code #	
For corners IOSCO	Located	d in:	- 0 -
1. Public Land Survey	T 24N	R 9E 2	98-51
	Ť Ť	R R	STATE OF MICHIGAN IOSCO COUNTY FILED
2. Property Controlling	s T	R	FILED
in Section	s T	R	10 DEC 98 2:55 P.M.
3. Miscellaneous	s T	R	BONITA N. COYLE
Property in Sec.	s T	R	REGISTER OF DEEDS
4, Lot No.	, Recorded Plat		a 17th Niveshay
a n' sa Claima			Register of Deeds Stamp & File Number
5. Private Claims			ABCDEFGHIJKLM
I, WILLIAM E. WOODS P.S., in a field survey on NOV 17, 1998 do hereby state 1			
			2 - 6 + 5 + 4 + 3 + 2 1
			4 - 7 - 8 - 9 - 10 - 11 - 12
Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by			6 -18 -17 -16 -15 -14 -13
			7
a Decree of a Court of Law; established,		re-established, monumented, recovered, found as	8 -19 -20 -21 -22 -23 -24
expressed below:			9
•			10 -30 -29 -28 -27 -26 -25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			11
on this certificate.			12 -31 -32 -33 -34 -35 -36
			13
A. Description of orig	ginal monument and	d accessories and/or subsequent restoration:	
1843: ORIGINAL GOVERNMEN		TO TO TO V DINE	
1843; ORIGINAL	GOAEKIMMETAL 140		
PLA		PLAT OF OSCODA BE	EACH LIBER 1 PAGE 28
1915: H. BELKNAP 1956: R.J. COOKE SUPERVISOR'S PLAT OF		OF EAST BREWSTER PARK LIBER 7 PAGE 23-24	
1956; R.J. COOK	L		
1			hing corner:
B. Description of co	rner evidence found	d and/or method applied in restoring or reestablish	THE STATE OF STREET
AGAMDER CORN	IER NOT FOUND SE	ET WITTNESS CORNER 294.61 EAST OF MEANE	DER CORNER ON SECTION LINE.
MEANDERCOID			
			WHITE OF MICHGAR
			WOODS *
		and accessories established to perpetuate locating	the position of the corne the position of the corne woods PROFESSIONAL SURVEYOR No. 25882 ER P.A. ING
C. Description of monument for corner and acceptance 5/8 BAR & REMON CAP		MARINE TO THE STATE OF THE STAT	No.
6" JACK PINE N 57° E 12.11		ACCEPTED BY THE IOSC SURVEY PEER GROUP	4S THE 25882
6" JACK PINE N 34° E 8.68		CERTICIAL CORNER UND	ER P.A.
8" JACK PINE N 90° W 11.48		145 OF 1990 AT A MEETI HELD ON 9-22-98	PROFESSIONAL SURVEYOR NO. 25882 PROFESSIONAL SURVEY NO.
O MONTHAL		A	*****