

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 42N R 31W	16 (GCDB 560600)
	S 1 T 42N R 31W	L2 (GCDB 640640)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2				
3													
4	7		8		9		10		11				
5													
6	18		17		16		15		14				
7													
8	19		20		21		22		23				
9													
10	30		29		28		27		26				
11													
12	31		32		33		34		35				
13													

I, Stephan J. Szyszkoski, in a field survey on 16 04/23/14
L2 04/24/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 2) East 1/16 corner between Sections 2 and 11. Not previously monumented.

(L2) Center of Section 1. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 2) Established the position for the corner midway and on the Section line between Section
corner 1315.41' east and 1/4 corner 1315.41' west.

(L2) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners. The position for the corner falls on the physical centerline of Camp 5 Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
21" R.Pine N11°W 33.5' mrkd "1/16S BT"
9" Spruce N77°E 24.25' do
5" Maple S46°W 39.7' do
12" R.Pine N73°W 52.4' do
Set sq'd cedar post adjacent.
E= 7911506.541 N= 142355.981

(L2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap 6"
below the surface of Camp 5 Road.
Set measuring nail with MDNR tag in the side of:
10" R.Pine N49°E 44.05' mrkd "C1/4 BT"
12" R.Pine S78°E 44.85' do
14" R.Pine N88°W 33.2' do
13" W.Pine N31°W 55.4' do
Set sq'd cedar post w/ location poster 24' West.
E= 7912728.929 N= 143142.970

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/07/2014

For the Michigan Department of Natural Resources, Forest Resources Division