

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 42N R 31W	6
	S T R	(GCDB 560660)
	S 1 T 42N R 31W	8
	S T R	(GCDB 620640)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/21/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 2) Northeast 1/16 corner, Section 2. Not previously monumented.

(8-Sec. 1) Center-West 1/16 corner, Section 1. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 2) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

(8-Sec. 1) Established the position for the corner midway and on a straight line between 1/4 corner
1329.26' west and the Center of Section 1 1329.26' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" W.Spruce N40°W 16.0' mrkd "1/16S BT"
5" W.Spruce N45°E 32.8' do
4" B.Spruce S69°E 47.8' do
5" B.Spruce S51°W 22.1' do
Set sq'd cedar post adjacent.
E= 7911523.470 N= 143566.648

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Maple N10°E 8.9' mrkd "1/16S BT"
6" R.Pine S12°E 6.55' do
5" Maple S46°W 9.0' do
7" R.Pine N75°W 11.7' do
Set sq'd cedar post adjacent.
E= 7912323.896 N= 143150.099

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/07/2014

For the Michigan Department of Natural Resources, Forest Resources Division