

**FEB 21 2001**

**SECTION**

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12:49

*L.C. Records: 1.8, P. 195*

*Robert A. Goodreau*  
REGISTER OF DEEDS

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 42N R 31W	A-3 ✓
	T 42N R 32W	M-3
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on March 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

A-3/M-3 Original corner established by William Burt, U.S. Deputy Surveyor, on 31 July 1846  
Original corner: Spruce post

Original witnesses: Tamarack 4 N41E 135 links  
Spruce 3 N18W 36 links  
Y. Pine 20 S30.5W 231 links

1" ID iron pipe w/ 4" aluminum cap, set by Arthur O. Enger, who replaced a 2" iron pipe and an old 3" x 3" squared post set by an unknown party. Enger replaced the pipe on 12 October 1970 (Liber 1, Page 55).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-3/M-3 Found corner as described by Enger.

Found witnesses recorded as: Jack Pine 10 S25°W (mag.) 147.9 ft. "S12, NBT"  
B. Spruce 4 N25°W (mag.) 66.0 ft. "S1, NBT"

Corner record research on file with county representative.

**PEER GROUP APPROVED**

*Robert A. Goodreau*  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-3/M-3 Accepted corner as found.

Witnesses: 16d nail in 4" Black Spruce N 25° W, 66.0'  
16d nail in E. face 4" Black Spruce N 64° E, 19.25'  
16d nail in W. face 4" Black Spruce S 15° W, 22.70'  
16d nail in W. face 4" Black Spruce N 41° W, 9.62'  
Sign post S 30° E, 0.90'

Signed by *Robert A. Goodreau*  
Surveyor's Michigan License No. 43053

Date July 1, 2000

