

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM12:49

L.C. Records, L. 8, P. 197

Edith A. Sackett
COUNTY OF IRON

For corners in

Iron

(County)

Located In:

Corner Code #

1. Public Land Survey

T 42N R 31W

B-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert A. Goodreau in a field survey on March 22, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-5 Original corner established by John Burt, U.S. Deputy Surveyor, on 7 August 1849

Original witnesses: Y. Pine 16 N63E 55 links

Y. Pine 16 S4W 23 links

3/4" ID iron pipe set by Murray Yates RLS off an original Norway Pine bearing tree on 3 December 1953 (Liber 2, Page 16) and described by Keith L. Sackett RLS on 16 August 1985 (Liber 5, Page 106).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5 Found corner as described by Sackett.

Set 5/8" iron pipe with 3.5" aluminum cap inside found 3/4" ID iron pipe.

Found witnesses recorded by Sackett as: 4" Red Pine N60W 10.9 ft. 1/4S, NBT
10" Jack Pine S47W 3.6 ft. 1/4S, NBT
4" Jack Pine S12E 29.2 ft. 1/4S, NBT
Pine stump w/ old notch S04W 15.4 ft.

Corner record research on file with county representative.

PEER GROUP APPROVED

Iron County Rep 11-14-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 Accepted corner as found.


Witnesses: Set 16d nails in above bearing trees at recorded distances.
16d nail in N. face 7" Jack Pine N 77° E, 16.55'
Sign post East 1'

Signed by

Robert A. Goodreau

Date July 1, 2000

Surveyor's Michigan License No. 43053



LIBER

8

PAGE

197