

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron (County)	Located in:	Corner Code #
1. Public Land Survey		T <u>42N</u> R <u>31W</u>	<u>G-2</u>
		T _____ R _____	_____
		T _____ R _____	_____
		T _____ R _____	_____
2. Property Controlling in Section	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM12:49

L.C. Records: L. 8, P. 203

Robert A. Goodreau
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert A. Goodreau in a field survey on May 9, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5			4		3		2	1
3												
4		7		8			9		10		11	12
5												
6		18		17			16		15		14	13
7												
8		19		20			21		22		23	24
9												
10		30		29			28		27		26	25
11												
12		31		32			33		34		35	36
13												

A. Description of original monument and accessories and/or subsequent restoration:

G-2 Original corner established by John Burt, U.S. Deputy Surveyor, on 7 August 1849
Original corner: Sugar post
Original witnesses: W. Pine 16 N47E 30 links
Cedar 12 S28W 12 links

1" I.D. x 36" iron pipe w/ 3.5" aluminum cap placed by Arthur O. Enger RLS, by proportionate measurement, on 13 June 1974.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-2 Found corner as described by Enger

Found witnesses recorded as:

W. Spruce 15 S17°W (mag.) 9.1 ft. "1/4S, NBT"
W. Spruce 18 S68°E (mag.) 34.0 ft. "1/4S, NBT"

Corner record research on file with county representative.

PEER GROUP APPROVED

Robert A. Goodreau 11-14-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-2 Accepted monument as found.

Witnesses: 14" spruce S 64° E, 34.64'
14" spruce S 19° W, 9.35'
4" balsam fir S 88° W, 19.4' (NBT)
6" cedar N 82° E, 53.35' (NBT)
sign post 1' South

Notes: Corner is on edge of cuttings, West of beaver pond.

Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

