

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 6 T 42N R 31W C-N-S 1/64	
	S 6 T 42N R 31W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2				5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/07/2009 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-N-S 1/64, Sec. 6) 1/64 corner south of the Center of Section 6, being the SW corner of the N1/2 of the NW1/4 of the SE1/4 of Section 6. Not established in the original survey.

(8-Sec. 6) West 1/16 corner, Sec. 6. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-N-S 1/64, Sec. 6) Established the corner midway and on a straight line between Center of Section 6 and 1/16 corner #12, 666.21' north and south.

(8-Sec. 6) Established the corner on a straight line between Center of Section 6 1313.55' east and 1/4 Corner 1300.41' west, being 20.00 chains, proportionate to the original record, west of the Center of Section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-N-S 1/64) 1"IDx32" I.P. with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
13" W.Pine S70E 22.6' mrkd "1/64S BT"  
6" R.Pine S36E 46.9' do  
3" R.Pine S47W 47.3' do  
8" R.Pine S82W 30.4' do  
Bearings are magnetic.

(8) 1"IDx32" I.pipe w/ 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" R.Pine N69E 22.05' mrkd "1/16S BT"  
7" J.Pine S14E 31.7' do  
5" R.Pine S14W 30.7' do  
12" R.Pine N80W 23.3' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 05/27/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

