

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. R. 31 XX W.	I4
2. PROPERTY CONTROLLING IN SECTION 10	T. 42 N. R. 31 XX W.	2 & 7
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, **Arthur O. Enger** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner I4: Y. Birch post (Not found. See B below)
Y. Pine 10 S82W 150 (Not found. No subsequent accessories found.)
Aspen 4 N57E 65 (" " " " " ")
Corners 2 & 7: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner I4: Re-established 5/30/74 on line between Sec. Cor. 40.274 ch. to N and to S.
Found a 1" O.D. iron pipe N13°W 12.68 ft., set after 1968 adjacent to a random line chainage reference tree, probably placed by an adjoining land owner.
Corner 2: Established 6/12/74 on line between Sec. Cor. 19.970 ch. E and 1/4 cor. 19.970 ch. W.
Corner 7: Established 5/30/74 on line between Sec. Cor. 20.137 ch. N and 1/4 cor. 20.137 ch. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Witnesses for Corner I4: Red Pine 7 N31°E (mag.) 29.3 ft. "1/4S, NBT"
Red Pine 4 N55½°W (mag.) 29.3 ft. "1/4S, NBT"
Witnesses for Corner 2: W. Birch 6 S55°E (mag.) 11.3 ft. "1/16S, BT"
W. Birch 9 S46°W (mag.) 26.0 ft. "1/16S, BT"
Witnesses for Corner 7: Jack Pine 12 S32°W (mag.) 50.4 ft., "1/16S, BT"
Red Maple 6 N27°W (mag.) 31.8 ft., "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE November 26, 1974
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

