

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 13 T 42N R 32W	5 (GCDB 640460)
	S 13 T 42N R 32W	L6 (GCDB 640440)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 12/22/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 13) Center-North 1/16 corner, Section 13. Not previously monumented.

(L6) Center of Section 13. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 13) Established the position for the corner midway and on a straight line between Quarter  
corner 1316.34' north and the Center of Section 13 1316.34' south.

(L6) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" J.Pine S63°E 35.25' mrkd "1/16S BT"  
11" J.Pine S89°W 17.65' do  
4" J.Pine N63°W 13.8' do  
10" Poplar N15°W 22.45' do  
E= 7903045.648 N= 140450.867

(L6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Balsam N24°E 8.25' mrkd "C1/4 BT"  
6" Poplar N75°E 40.0' do  
6" Balsam S27°E 22.35' do  
4" Balsam N76°W 3.65' do  
Set sq'd cedar post adjacent.  
E= 7903041.155 N= 140049.751

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 02/11/2015

For the Michigan Department of Natural Resources, Forest Resources Division