

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970 as Amended**

For corners in

Iron <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S 26 T 42N R 32W	8
	S 26 T 42N R 32W	11
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File  
Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Mar 22 2007

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

- (8-Sec. 26) West 1/16 corner, Section 26. Not established in the original survey.
- (11-Sec. 26) Southwest 1/16 corner, Section 26. Not established in the original survey.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

- (8-Sec. 26) Established the corner midway and on a straight line between 1/4 corner 1321.52' west and the intersection of 1/4 lines of Section 26 1321.52' east.
- (11-Sec. 26) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

- |  |   |
|--|---|
| (8) Set 1"IDx32" I.pipe with 4" alum.<br>MDNR cap. Set measuring nails in: | (11) Set 1"IDx32" I.pipe with 4" alum.<br>MDNR cap. Set measuring nails in: |
| 7" Poplar N88W 50.1' mrd "1/16S BT"  | 7" R.Pine North 52.3' mrd "1/16S BT"  |
| 7" Poplar N72W 32.6' do  | 15" R.Pine N84E 16.9' do  |
| 3" Poplar N56W 39.7' do  | 14" R.Pine S44E 20.2' do  |
| Distances above are to nail/MDNR tag.                                      | 17" R.Pine S14E 8.6' do   |
| Buried cable sign N64W 36.7'   | Bearings are magnetic. Distances are to                                     |
| Bearings are magnetic.   | nail with MDNR tag.   |



Signed by Stephan J. Szyszkoski  
 Surveyor's Michigan License No. 33986

Date 4/19/07

For the Michigan Department of Natural Resources, Office of Land and Facilities