

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>42N</u> R <u>35W</u>	<u>K-7</u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
2. Property Controlling	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
3. Miscellaneous	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
Property in Sec.	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:11

L.C. Records: L. 8, P. 296

*Robert J. Pisoni*  
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat           
5. Private Claims         

Section Corner to Sections 13, 14, 23, 24, T42N, R35W

I, Gary L. Pisoni, in a field survey on November 24, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 11, 1851 by Harvey Mellen, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Cedar	16"	S 85° W	13 links (8.58 feet)
Lynn	12"	S 14° E	29 links (19.14 feet)

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Don Amy & Team 11-30-2000

PEER GROUP APPROVED

COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

Found a P.K. nail located 1.5 feet West of the centerline of M-189 which runs North and South and in the centerline of a county road which runs East and West.

P.K. nail has been used for the past 20 years for various surveys in the surrounding area.

I accept the P.K. nail as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set one reference monument being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T42N, R35W, R.M., S-13, S-14, S-23, S-24, S 54 W, 50.86 feet, 2000, RLS 27457 from which I established the following new references:

R.M.	5/8" x 30" rebar	N 54°E	50.86 feet
Utility pole	#N70-1207	S 52°E	72.15 feet
Red Pine(dbl)	18"	S 56°W	74.26 feet
Utility Pole	#80-24480	N 57°W	58.38 feet
Steel sign post		N 54°E	51.36 feet

00-064

Signed by Gary L. Pisoni Date 11-29-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983  
REVISED OCT. 1995

