

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T <u>42NR</u> <u>35W</u>	<u>MC South of C8</u>
	T <u> </u> <u> </u>	<u> </u>
	T <u> </u> <u> </u>	<u> </u>
2. Property Controlling in Section	S <u>20</u> T <u>42NR</u> <u>35W</u>	<u>10</u>
	S <u> </u> T <u> </u> <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> <u> </u>	<u> </u>
	S <u> </u> T <u> </u> <u> </u>	<u> </u>

Register of Deeds Stamp & File
Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims

May 16 2006

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC South of C8) Meander corner between Sections 19 and 20 on the north bank of the Brule River. 1851 - Established by Harvey Mellen, DS: " S6'E between Sections 19 & 20 ... 72.90 Left bank of Brule River and set post. Fir 12 N2W 130 links". Found no subsequent record.
 (10-Sec. 20) South 1/16 corner between Sections 19 and 20. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC South of C8) The original post and accessories were not recovered. The position for the corner now falls in the Brule River. Reestablished the corner at indexed GLO record bearing and distance south of corner C7, said indexed bearing and distance being S 00 deg. 17' 26"E, 4794.07 feet (72.637 chains). The position for the corner is not monumented. Set a WITNESS CORNER on the Section line 136.85' north of the MC position. From the WITNESS CORNER monumented, found a 3/4" iron pin, not of record N 58 deg. 54'W, 128.31' distant, which I did not accept as marking the Section line location. From the MC, the water's edge (near flood stage this date) is 125' south.
 (10-Sec. 20) Established the corner at indexed GLO record bearing and distance south of corner C8, said indexed bearing and distance being S 00 deg. 17' 26" E (true) 1315.25' (GLO record = S6'E 20.00 chains).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set a 1"IDx32" I.pipe with 4" alum. MDNR cap for a MC 136.85' North of the MC. Set measuring nails in: 7" B.Ash S63E 28.2' mrkd "MCMC BT" 7" B.Ash S11E 13.9' do 8" Balsam N59W 11.0' do 8" B.Ash N39W 22.8' do Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with tag.	(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nails in: 5" Sugar S83E 20.2' mrkd "1/16S BT" 7" Sugar S42E 18.9' do 7" Sugar N87W 23.2' do 12" Sugar N70W 37.4' do Bearings are magnetic. Distances are to nail with tag.
--	--



Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 6/13/06