

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L. 8, P. 208

Robert A. Goodreau
REGISTERED PROFESSIONAL SURVEYOR

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 43N R 31W	C-7
	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert A. Goodreau in a field survey on March 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-7 Original corner established by John Burt, U.S. Deputy Surveyor, on 14 July 1849.

Original corner: Sugar post

Original witnesses: Y. Birch 24 S 65° W 19 links
Y. Birch 26 N 46° E 26 links

Arthur O. Enger RLS restored corner on 26 April 1974 using proportionate measurement in latitude and 2647.0 ft. E'ly of quarter corner for Sections 18 and 19 for departure (Liber 1, Page 305-306).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-7 Found 1" ID iron pipe w/ 3.5" aluminum cap set by Enger.

Found witnesses: Rock outcrops match description by Enger, but no chiseled (x)'s found as described.

Corner record research on file with county representative.

PEER GROUP APPROVED

Robert A. Goodreau 11-14-2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7 Accepted corner as found.

Witnesses: 5" W. Spruce N 56° W 14.22'
6" W. Spruce S 37° W 5.75'
5" W. Spruce N 12° W 5.90'
8" W. Spruce S 74° E 10.67'
Sign post South 1.0'

Note: All measurements taken to a nail in side of tree.

Signed by *Robert A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

