

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 43N R 32W	F2
	S T R	(GCDB 340640)
	S 4 T 43N R 32W	5
3. Miscellaneous Property in Sec.	S T R	(GCDB 340660)
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5					3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10/28/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F2) Center of Section 4. Not previously monumented.

(5-Sec. 4) Center-North 1/16 corner, Section 4. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F2) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.

(5-Sec. 4) Established the position for the corner on a straight line between the Center of Section 4 1329.34' south and the Quarter corner 1436.66' north, the position being 20.00 chains, proportionate to the dimensions derived from the original plat of this township, north of the Center of Sec. 4.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Sugar S73°E 39.85' mrkd "C1/4 BT"
5" Sugar S15°W 8.65' do
5" Sugar S83°W 5.2' do
6" Sugar N15°W no distance do
Set sq'd cedar post 1' northerly
The center of a N-S dirt road is 12' east.
E= 7898396.546 N= 152988.032

(5) Cemented 1/2"x10" rebar into a 3/4"x6" drill hole and cemented a 1"IDx10" I.pipe with a 2" alum. MDNR cap over the top of the rebar.
Set measuring nail with MDNR tag in the side of:
9" Sugar N14°W 11.54' mrkd "1/16S BT"
6" Ash N79°E 18.50' do
4" Sugar S25°E 12.20' do
5" Sugar N50°W 14.65' do
E= 7898404.888 N= 153393.066

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski Date 03/05/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division