

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 4 T 43N R 32W S _____ T _____ R _____ S 4 T 43N R 32W	1 (GCDB 320700) 6
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 360660) _____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6												
3													
4	7												
5													
6	18												
7													
8	19												
9													
10	30												
11													
12	31												
13													

I, Stephan J. Szyszkoski, in a field survey on 11/05/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 4) West 1/16 corner between Section 4 T43N-R32W and Section 33 T44N-R32W. Not previously monumented.

(6-Sec. 4) Northeast 1/16 corner, Section 4. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 4) Established the position for the corner midway and on the Township line between Section corner 1321.92' west and Quarter corner 1321.92' east.

(6-Sec. 4) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
2" Bl. Spruce N22°E 20.65' mrkd " X X "
6" Cedar S58°E 21.2' "1/16S BT"
6" Cedar S76°W 11.95' do
7" Cedar N34°W 25.4' do
Set sq'd cedar post adajcent.
E= 7898011.087 N= 153836.773

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N52°E 7.5' mrkd "1/16S BT"
7" Sugar S20°E 30.0' do
10" Basswood N87°W 22.8' do
6" Sugar N17°W 20.7' do
Set sq'd cedar post adjacent.
E= 7898806.299 N= 153388.277

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/05/2015

For the Michigan Department of Natural Resources, Forest Resources Division