

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 32W

M-11 ✓

T 43N R 31W

A-11

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

60 DEC -8 PM 1:06

L.C. Records: L. 8, P. 272

Robert L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Section corner to Sections 25 and 36, T43N, R32W

Section corner to Sections 30 and 31, T43N, R31W

I, Gary L. Pisoni, in a field survey on November 2, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5			4		3		2		1
3													
4		7		8			9		10		11		12
5													
6		18		17			16		15		14		13
7													
8		19		20			21		22		23		24
9													
10		30		29			28		27		26		25
11													
12		31		32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Fir Post

Original Bearing Trees:

Hemlock	10"	S 14° E	43 links (28.38 feet)
White Pine	14"	N 35° W	44 links (29.04 feet)

On July 14, 1849, John Burt, U.S. Deputy Surveyor established the following new bearing tree:

White Pine	18"	N 39° E	20 links (13.20 feet)
------------	-----	---------	-----------------------

On May 2, 1972, Arthur O. Enger, RLS DNR restored the corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" diameter aluminum cap stamped as follows: T43N, R32W, R31W, S-25, S-30, S-36, S-31, RLS 13581, recorded in Liber 1, Page 89, 90 of LC records.

1972 Bearing Trees:

Jack Pine	5"	S 63° E	91.2 feet
Jack Pine	4"	N 62 ½° E	12.5 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found existing bearing trees which were established by Robert Spear, Jr. RLS of Sundberg, Carlson and Associates.

Jack Pine	9"	N 16° E	44.15 feet
Jack Pine	14"	N 64° E	12.89 feet (A.O. Enger RLS)
Balsam	8"	S 44° W	4.68 feet
Jack Pine	9"	N 12° W	78.35 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel sign post	West	0.85 feet
-----------------	------	-----------

00-040

Signed by

Gary L. Pisoni

Date

11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISOR MAY 14, 1975

REVISOR JAN., 1983

REVISOR OCT., 1996

LIBER 8 PAGE 272

