SURVEY & REMONUMENTATION

FEB 21 2001

COMMENCING YEAR 2000 RECEIVED FOR RECORD IRON COUNTY, MICHIGAN

SECTION	LAND COR	NER RECORD	ATION CERTIFICAT	TE 00 DEC-5 PH12	:50 L.8, P.218	
For corners in	i ming riequ	inement of Ac	1	L.A. B	*	
Iron (County)	Located In:	Corner Code	e #	CONTRACTOR OF MAN	lee) 08	
1. Public Land Survey	T <u>44N</u> R <u>33W</u> T R T R	<u>K-5</u>				
Property Controlling in Section S. Miscellaneous S. Property in Sec. S.	TRTRTRTRTRTR			Register of Deeds S	itamp & File Number	
4. Lot No, Recorded 5. Private Claims	l Plat		,-	1 2 6 5 4	G H I J K L I	
I, Robert A Goodreau in a field requirements of P.A. 74, Michiga above were in conformance with manual of survey instructions of the Management or by a decree of a 3, 4 and 5 above were in conform or by a Decree of a Court of Law, as expressed below:	on P.A. of 1970, the corn in regulations and rules the United States Depart Court of Law and /or that hance with the rules of the cetablished, re-established;	er points mention therefore as req tment of the Intel the corner point e Michigan Board hed, monumente	ned in lines 1 and 2 uired in the current rior, Bureau of Land s mentioned in lines d of Land Surveyors ed, recovered, found	3 4 -7 -8 -9 -5 6 -18 -17 -16 -7 8 -19 -20 -21 -9 10 -30 -29 -28	-101112 -1514	
NOTE: Not more than 2 come certificate.	ers, all in the same town	n and range, ma	y be recorded on this	11	34 35 36	
A. Description of original monur	ment and accessories ar	nd/or subsequent	restoration:			
• •	ished by Guy A. Carletor					
Original witnesses:	W. Pine 20 N55E W. Pine 16 S25E	46 links 26 links			·	
	,	. •				
B. Description of corner eviden	nce found and/or method	applied in restor	ring or reestablishing c	orner:		
K-5 Found 1* ID iron pipe	set by Billy D. Buckler F	ILS, who replace	d a found 1.5" iron pipe	e, on 4 March 1957 (Liber	2, Page 192).	
Found witnesses recorded by Buckler as: 10" W. Pine 10" W. Pine N51E 10.5 links 10" W. Pine S11W 47 links			PEER GROUP APPRO	OVED		
Corner record research on file with county representative.			COUNTY REPRESENT	-1 1 - 1-6/2/21		
C. Description of monument for	corner and accessories	established to p	erpetuate locating the	position of the corner:		
K-5 Accepted corner as fo	und.					
20" W. Pir 20" W. Pir	20" W. Pine N 76° E 7.85' Note: M 20" W. Pine S 53° E 22.60' 20" W. Pine S 16° W 31.40'			Measurements taken to a nail in side of witnesses.		
8" Sugar Sign post	S 03° E 6.14' West 1'		•			
Signed by	bl	Date	July 1, 2000			
Surveyor's Michigan License No	o, <u>43053</u>			The firm	Walley Control	