

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 33W	K-10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PH 1:10  
L.P. Records: L.S., P. 287  
*Gary L. Pisoni*  
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Quarter Corner to Sections 25 and 26, T44N, R33W

I, Gary L. Pisoni, in a field survey on November 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in June, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.  
Original Corner; Wood Post

Original Bearing Trees:

Yellow Birch	14"	N 60° W	42 links (27.72 feet)
Yellow Birch	12"	S 24° E	23 links (15.18 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PEER GROUP APPROVED  
*Gary L. Pisoni 11-30-2000*  
COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

Restored the corner position by single proportionate measurement and on line between the Northeast and Southeast Section corners of Section 26.

Found a fence corner which bears S 00° 53'W and 45.34 feet from the single proportioned quarter corner.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar, flush with ground surface, with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, 1/4, S-25, S-26, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	7"	N 73° E	25.42 feet
White Spruce	14"	S 01° W	37.00 feet
White Spruce	12"	S 85° W	29.96 feet
White Spruce	10"	N 46° W	23.10 feet
Steel sign post		S 40° E	0.65 feet

00-055

Signed by

*Gary L. Pisoni*

Date

11-29-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

