

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 05/07/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 2) South 1/16 corner between Sections 1 and 2. 1957 - Established by Billy D. Buckler RLS midway and on line between Section corner 1-2-11-12 to south and 1/4 corner to north. Set 1/2"x36" iron bar and wood post. 10" R.Pine N40°E 44.5 links, 8" Tamarack S62°E 21 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 2) Found a 1/2" dia. iron bar projecting 9" a.g., top mushroomed, at record bearing and distance from the 1957 BT R.Pine N40°E in good condition with overgrown blazes. Placed a plastic cap "MI DNR PS33986" atop the bar. Made no attempt to confirm the accuracy of the position of this monument. This is being recorded in order to update the accessories and preserve the position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Found 1/2" dia. iron bar. Set plastic cap PS33986 on top. Set measuring nail with MDNR tag in the side of:
21" R.Pine N43°E 29.7' old blazes (1957 BT)
4" B.Spruce N74°E 19.5' mrkd "1/16S BT"
7" Balsam S38°W 5.05' do
6" B.Spruce S76°W 14.25' do
Set sq'd cedar post adjacent.
E= 7892943.805 N= 162345.123



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83 (2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by [Signature] Date 08/17/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division