

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

1. Public Land Survey

T 44N R 34W

C-2

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

00DEC-8 PM 1:02

L.C. Records: L. 8, P. 250

Gary L. Pisoni
REGISTERED BY RECORDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Quarter Corner to Sections 5 and 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	●	5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		16		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 18, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Spruce 12" S 37° W 20 links (13.20 feet)

Spruce 6" N 64° W 38 links (25.08 feet)

On 11/10/76, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 3 3/4" diameter aluminum cap stamped as follows: T44N, R34W, 1/4, S-6, S-5, 11/10/76, RLS 13581, recorded in Liber 1, page 521 of LC records.

1976 Bearing Trees:

Elm 8" N 03° E 17.9 feet

Elm 6" S 56° E 17.0 feet

PEER GROUP APPROVED

Gary L. Pisoni 11-30-2000

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/4/2000, found the above described monument.

Monument is 12" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Ash 9" S 55° E 17.14 feet

Balsam 9" N 55° E 30.19 feet

Ash 7" S 13° W 28.94 feet

Balsam 5' N 59° W 16.30 feet

Steel sign post N 37° E 1.28 feet

00-018

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1974

