

# SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM12:50

L.C. Records: L. 8, P. 221

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

*Edwin L. Lippala*  
REGISTERED PROFESSIONAL SURVEYOR

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 43N R 36W	B-1
	T 44N R 36W	B-13 ✓
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-1/B-13 Original corner established by Austin Burt, U.S. Deputy Surveyor, in 1847.

Original witnesses:	Sugar Maple	6"	N 73° E	26 links
	Sugar Maple	15"	N 09° W	37 links

Donald D. Lappala RLS restored corner position on 10 September 1964 by marking a cross (x) in the pavement using State Highway project plans and an existing reference monument. He also set a 2" x 5' concrete filled iron pipe w/bronze tablet as a reference monument (Liber 3, Page 284).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PEER GROUP APPROVED

*Donald D. Lappala* 11-14-2000  
COUNTY REPRESENTATIVE

B-1/B-13 Found reference monument set by Lappala described as North 44.9'.

Found witnesses recorded by Lappala as:	6" Sugar Maple	N 27° W	53.1'	(80.5 links)
	7" Yellow Birch	N 0°-30' W	51.6'	(78.2 links)
	8" Yellow Birch	S 24°-30' E	77.4'	(117.3 links)

No corner found. Restored corner position with PK nail in pavement using found bearing trees and found reference monument.

Corner record research on file with county representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-1/B-13 PK nail in pavement.

Witnesses:	9" Maple	N 24° W	52.72' (USFS BT sign)
	10" Y. Birch	N 01° W	51.25'
	14" Y. Birch stub	S 21° E	77.20' (USFS BT sign)
	Mon. box & 1/2" bar	N 85° E	8.06'
	Sign post 1' North of reference monument		

Note: Measurements taken to a nail in side of witnesses.

Signed by R. A. Goodreau

Date July 1, 2000

Surveyor's Michigan License No. 43053

