

# SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L. 8, P. 223

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

*Robert A. Goodreau*  
REGISTERED PROFESSIONAL SURVEYOR

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 43N R 36W	D-1
	T 44N R 36W	D-13 ✓
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5		4		3		2		1		
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

D-1/D-13 Original corner established by Austin Burt, U.S. Deputy Surveyor, in 1847.

Original witnesses: Sugar Maple 8" N 70° E 32 links  
Sugar Maple 12" N 65° W 9 links

Donald D. Lappala RLS restored corner position w/ an (x) in the pavement on 23 September 1964 using State Highway project plans and an existing reference monument. He also set a 2" x 5' conc. filled reference monument w/ bronze tablet (Liber 3, Page 286).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-1/D-13 Found PK nail in centerline of U.S. Highway 2 as described by Gary Pisoni RLS.

Found reference monument set by Lappala described as: South 57.3'

Found witnesses recorded by Lappala as: 3" Yellow Birch N 25° E 70.7' (107.1 links)  
4" Yellow Birch S 51°-30' W 106.5' (161.4 links)

Corner record research on file with county representative.

PEER GROUP APPROVED

*Robert A. Goodreau* 11-14-2000

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1/D-13 Accepted corner as found.

Witnesses: 9" Yellow Birch N 32° E 70.71' (slope) +16°  
8" Yellow Birch S 56° W 106.32' (slope) +11°  
½" iron pin w/ UPEA cap & sign post S 45° E 86.27'  
Monument box West 19.3'  
Sign post 1' North of reference monument

Note: Measurements taken to a nail in side of witnesses.

Signed by RA. Good  
Surveyor's Michigan License No. 43053

Date July 1, 2000

