

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 21 T 45N 34W	7
	S 21 T 45N R 34W	4-5
	S T R	(SMC btwn Govt Lots 1 and 2)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on SMC 4-5 12/20/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7) North 1/16 corner between Section 21 and 22. Previously monumented in 1965 by Neil Sperhake RLS
7876.

(SMC) Special Meander Corner between Government Lots 1 and 2, on the North 1/16 line of Section 21
between 1/16 corners #3 and #5. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7) Found a 1"ID I.pipe with 4" alum. cap appropriately stamped to identify the corner and "Sperhake
RLS 7876 11-4-65". The monument is substantially at the correct position, midway and on line
between Section corner north and Quarter corner south. Accepted same as a careful and faithful
determination of the position of the corner.

(SMC) Established a witness corner to the position for the corner near the east bank of the Net
River, on a straight line between 1/16 corner #3 2048.18' west and 1/16 corner #5, 606.00' east.
The water's edge of the Net River is approx. 50' west of the corner position. The position is not
intended to mark the OHWM of the Net River.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Fd. 1"ID I.pipe with 4" Kimberly-Clark cap.
Set measuring nail with MDNR tag in the side of:
8" Maple N11E 13.95' mrkd "1/16S BT"
8" Maple S71E 2.95' do
16" Y.Birch S38W 16.6' do
9" Maple S82W 8.8' do
Set sq'd Cedar post adjacent.
N=168267.691 E=7880231.029

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
The cap is marked "POL Sec 21 N---N".
Set measuring nail with MDNR tag in the side of:
14" Cedar N03E 27.5' mrkd "POL BT"
14" Cedar N30E 35.2' do
8" Ash S48E 14.05' do
6" Ash S33W 23.3' do
Set sq'd cedar post adjacent.
N=168271.681 E=7879242.011

Bearings are magnetic. Coordinates are MCS83, in meters

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/14/2013

For the Michigan Department of Natural Resources, Forest Resources Division

