LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #	
1. Public Land Survey	TR TR		
2. Property Controlling in Section	S 4 T 45N R 34W S T R S 4 T 45N R 34W	(GCDB 320620)	
3. Miscellaneous Property in Sec.	S T R S T R	SMC east of #3 (GCDB 304660)	
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G H I J K L M
above were in conformance with instructions of the United States I a Court of Law and /or that the other rules of the Michigan Board	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require. Department of the Interior, Bureau of Larcorner points mentioned in lines 3, 4 and 3 of Land Surveyors or by a Decree of	d in the current manual of survey nd Management or by a decree of 5 above were in conformance with	5 6 18 17 16 15 14 13
NOTE: Not more than 2 corn on this certificate.	ered, found as expressed below: ers, all in the same town and range,	may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 4) Southwest 1/16 corner, Section 4. A monument was placed near the position for the corner by G.L.Pisoni, PS during a survey of Gov't Lots 1 and 2, date not known.

(SMC east of #3) Witness Corner to a Special Meander corner on the East shore of Porter Lake at its intersection with the North 1/16 line of Section 4. Previously established by G.L.Pisoni PS 27457.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 4) Established the position for the corner at the intersection of 1/16 lines. The South 1/16 line is parallel to the weighted mean bearing of the W1/2 of the E-W 1/4 line and the W1/2 of the south line of the Section. The West 1/16 line is a straight line between 1/16 corners #8 and #15. From the position thus established, I found a 5/8" capped rebar, PS #27457, 15.3' south, which I did not accept as marking the position for the corner and which I drove flush to the ground surface.

(SMC east of #3) A subdivision of the NW1/4 of this section could be made in several ways and the choice of methods is more complicated than normal due to the lack of harmony between conditions on the ground and their representation on the face of the U.S. plat. I found a 5/8" capped rebar PS I found a 5/8" capped rebar PS #27457, in good condition, approx. 195' east of the U.S. position for 1/16 corner #3, and accepted same as a careful and faithful determination of the location of the North 1/16 line. From this Witness Corner monument, the edge of vegetation along the east side of Porter Lake is 29' west; and the water's edge is 33' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Sugar S68°E 12.85' mrkd "1/16S BT" 8" Sugar S15°E 6.5' do 5" Sugar S63°W 5.0' do 8" Sugar N03°W 15.0' do Set sq'd cedar post adjacent. E= 7879113.820 N= 172272.879	(WC) Drove a 1"IDx28" I.pipe cap over the found 5/8" rebarsed for the found 5/8" repair for the found 5/8" rebarsed for the found 5/8" repair for the found 5/	r. tag in the side of: rkd "WC BT" do do do
--	--	--

Bearings are magnetic.	Coordinates are	MCS83 in meters,	NAD83 (2011)	Epoch 2010.00	datum
Coord. Ref.=	NGS PID RL0476:	N= 196482,411 m.	E= 7879234	516 m	

Signed by Date 09/15/2015

Surveyor's Michigan License No.

33986 For the Michigan Department of Natural Resources, Forest Resources Division

LAND

SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF